



Hot Spot
HS3
Pilots of Code F aircraft must take care - Link 28 East of Taxiway Alpha is NOT Code F compliant.

CHANGE (6/18): MAG VAR. TWY S RIGHT TURN CENTRELINE TO HOLDS SB & SB3 REMOVED.

AERO INFO DATE 23 FEB 18